Pursanova Limited - Kochi Prefectural Haruno Higashi Elementary School

Installed date: April 5th 2005 www.pursanova.com





1st floor pump room ST-1 2 5 L

Entrance still cock







Still cock Inside valve

Picture taken 4/5


Still cock drainage





Picture taken 4/28





Rust has dissolved, and black dots have diminished in drainage.

Water tank and pipe Water tank oxygen level





Water tank internal wall and bottom

Arrow, you can see the rust mass







Indoor pump water tank

Date	Temperature	Water Temperature	Saturated-dissolved oxygen	Current saturated-dissolved oxygen
4/5	20°C	14.5℃	9.76 mg/L	10.1 mg/L
4/12	23°C	16.2℃	9.56 mg/L	10.2 mg/L

1st floor sink

Picture taken September, 2004

Picture taken April 2005





Obvious improvements seen from September to April





Again, obvious change in the rust and sludge!

Elevated reservoir





Picture taken 4/5/2005



Picture taken 4/28/2005



In 23 days, rust sedimation decreased as well as sludge.

		Elevated reservoir				
Date	Outdoor temperature	Water temperature	Saturated-dissolved oxygen	Current Saturated-dissolved oxygen		
4/5	20°C	14.5°C	9.76 mg/L	10.1 mg/L		
When the elevated reservoir is left for a period of time, the saturated oxygen is 8 mg/L						
4/12	23°C	16.7°C	9.37 mg/L	10.3 mg/L		
4/28	25℃	17. 8℃	9. 18mg/L	10. 8mg/L		