

Takarazuka-Sanda Hospital

Location: Hyogo

Installed date: October, 2006

Model:

PUR-ST-100L x 1



Well water tank



PUR-ST-100L installed



Picture of the well water tank (used for bathroom and cleaning) of the hospital

Well water 1



Since the first well, did not produce much water, we have decided not to use this well water. We have asked to clean and remove impurities flowing at the top of the well as seen in the picture.

Well water 2



You can observe the black condensation at the bottom of the water tank. We will observe this black condensation and water quality after the installation. We are hoping to see the differences in the following areas: Urinary calculus, pipe clogging, and general odor.